

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspection:				
Company	David Spillman			
OGM	Karl Houskeeper			

Inspection Report

Permit Number:	C0070039
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, January 25, 2017
Start Date/Time:	1/25/2017 9:00:00 AM
End Date/Time:	1/25/2017 1:30:00 PM
Last Inspection:	Tuesday, December 12, 2017

Inspector: Karl Houskeeper,

Weather: <u>Clear Skies, Temp. 15 Deg. F.</u> InspectionID Report Number: 5747

Accepted by: DHADDOCK 1/30/2017

Permitee: CANYON FUEL COMPANY
Operator: CANYON FUEL COMPANY
Site: DUGOUT CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	9,568.00
Total Disturbed	106.88
Phase I	37.00
Phase II	19.00
Phase III	1.82

Mineral Ownership Types of Operations

✓ Federal	✓ Underground
✓ State	Surface
☐ County	Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

-Karl R. Nouskeeper

Inspector's Signature:

Date

Wednesday, Janu



Permit Number: C0070039 Inspection Type: PARTIAL

Inspection Date: Wednesday, January 25, 2017

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.

 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.1	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070039
Inspection Type: PARTIAL

Inspection Date: Wednesday, January 25, 2017 Page 3 of 3

2. Signs and Markers

Observed the identifications signs associated with the Dugout Mine. The signs contained the name, address, phone number and mining permit number as required by regulation. The signs were compliant.

3. Topsoil

Topsoil storage piles are snow covered.

4.a Hydrologic Balance: Diversions

All diversions are snow covered. The depressions of where the diversions are, is still visible.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment pond is snow covered.

7. Coal Mine Waste, Refuse Piles, Impoundments

Snow from the mine site is being hauled to the waste rock site.

Waste rock site appeared stable.